

ATTN: NDA CON UNIT

WATERBURY, CT 06705

WATERBURY, CT 06705

WATERBURY, CT 06705

RECEIVED
JUN 15 9 45 AM '92
EPA
REGION VI
OFFICE OF ACTION
ADMINISTRATIVE



1901 June 08

Mr. Fran Phillips
Environmental Protection Agency
First International Building
1201 Elm Street
Dallas, Texas 75270

Certified #P20 0805345 - EPA
Certified #P20 0805346 - TDOH

*ALUMINUM COMPANY OF
AMERICA - ANDERSON WORKS*

Dear Ms. Phillips:

TXD068980267

RE: NOTIFICATION OF HAZARDOUS WASTE SITE

As required by the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (Superfund), attached is a completed Notification of Hazardous Waste Site for this location.

Very truly yours,

O. E. Wilkinson
O. E. Wilkinson

OEW:je

Attachment

cc: Jack C. Carmichael, P.E. Director
Division of Solid Waste Management
Texas Department of Health
1100 West 49th Street
Austin, Texas 78756



SUPERFUND FILE

JUL 14 1992

REORGANIZED

EPA Notification Hazardous Waste Site

TXS-620-001-160

000001

United States
Environmental Protection
Agency
Washington, DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

JUN 10 1981

6AEP

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Aluminum Company of America

Street P. O. Box 558

City Palestine

State Texas Zip Code 75801

B Site Location: TXD 06 PPP 0267

Enter the common name (if known) and actual location of the site.

Name of Site Anderson County Works

Street P. O. Box 558, Hwy 79 East

City Palestine

County Anderson

State Texas Zip Code 75801

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Wilkinson, O. E., Environmental Superintendent

Phone 214/729-2281

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1977

To (Year) 1980

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify)

Source of Waste:
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper / Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron / Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating / Polishing
- 10. ☐ Military / Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary / Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab / Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

D002		
D003		

SUPERFUND
FILE

JUL 20 1992

REORGANIZED

Notification of Hazardous Waste Site

Side Two

F Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site. In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons. In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

- 1 ☐ Piles
- 2 ☐ Land Treatment
- 3 ☒ Landfill
- 4 ☐ Tanks
- 5 ☐ Impoundment
- 6 ☐ Underground Injection
- 7 ☐ Drums, Above Ground
- 8 ☐ Drums, Below Ground
- 9 ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 600,000

gallons 4,488,600

Total Facility Area

square feet

acres 1.6

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

This inactive site is called the #1 Dry Solids Pond and is registered with the Texas Department of Water Resources as a disposal facility consists of 3 foot 10-7 cm/sec clay liner, leachate collection system, 20 mil synthetic liner, and a one foot clay liner cover. Wastes were deposited in this facility from May, 1977 to September, 1980.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Aluminum Company of America

Street P. O. Box 553

City Palestine

State Tex Zip Code 75801

Signature *O. E. Wilkinson*
O. E. Wilkinson

Date 06/08/81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other